

Silicon identification

This errata sheet applies to revision Z of STMicroelectronics STM32F318x8 products. These products feature an ARM® 32-bit Cortex®-M4 CPU with FPU core, for which an errata notice is also available (see [Section 1](#) for details).

[Section 2](#) gives a detailed description of the product silicon limitations.

The products are identifiable as shown in [Table 1](#):

- By the revision code marked below the order code on the device package
- By the last three digits of the Internal order code printed on the box label

Table 1. Device identification^{(1) (2)}

Order code	Revision code ⁽²⁾ marked on device
STM32F318x8	"Z"

1. The REV_ID bits in the DBGMCU_IDCODE register show the revision code of the device (see the STM32F318x8 reference manual for details on how to find the revision code).

2. Refer to STM32F318x8 product datasheet for details on the device marking.

The full list of part numbers is shown in [Table 2](#).

Table 2. Device summary

Reference	Part number
STM32F318x8	STM32F318C8, STM32F318K8

Contents

1	ARM® 32-bit Cortex®-M4F limitations	5
1.1	Cortex®-M4F interrupted loads to stack pointer can cause erroneous behavior	5
1.2	VDIV or VSQRT instructions might not complete correctly when very short ISRs are used	6
2	STM32F318x8 silicon limitations	7
2.1	System limitation	8
2.1.1	Wakeup sequence from Standby mode when using more than one wakeup source	8
2.2	ADC limitations	9
2.2.1	Sampling time shortened in JAUTO auto delayed mode	9
2.2.2	Injected queue of context is not available in case of JQM = 0	9
2.2.3	Load multiple not supported by ADC interface	9
2.2.4	ADEN bit cannot be set immediately after the ADC calibration is done	10
2.3	SPI peripheral limitation	10
2.3.1	SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI is under DMA transaction near the end of transfer or end of transfer '-1'	10
2.4	I ² C peripheral limitations	11
2.4.1	10-bit slave mode: wrong direction bit value after Read header reception	11
2.4.2	10-bit combined with 7-bit slave mode: ADDCODE may indicate wrong slave address detection	12
2.4.3	Wakeup frames may not wakeup the MCU mode when STOP mode entry follows I ² C enabling	13
2.4.4	Wrong behaviors in Stop mode when wakeup from Stop mode is disabled in I2C	13
2.4.5	Wakeup frame may not wakeup from STOP if $t_{HD(STA)}$ is close to $t_{su(HSI)}$ in Fast-mode and Fast-mode Plus	13
2.4.6	Wrong data sampling when data set-up time ($t_{SU;DAT}$) is smaller than one I2CCLK period	14
2.5	I2S peripheral limitations	15
2.5.1	In I2S slave mode, WS level must be set by the external master when enabling the I2S	15
2.6	USART peripheral limitation	15

2.6.1	When PCLK is selected as clock source for USART1, PCLK1 is used instead of PCLK2	15
2.7	GPIO peripheral limitation	16
2.7.1	GPIOx locking mechanism is not working properly for GPIOx_OTYPE register	16
Revision history		17

List of tables

Table 1. Device identification 1

Table 2. Device summary 1

Table 3. Cortex®-M4F core limitations and impact on microcontroller behavior. 5

Table 4. Summary of silicon limitations. 7

Table 5. Document revision history. 17



1 ARM® 32-bit Cortex®-M4F limitations

An errata notice of the STM32F318x8 core is available from the following web address:
<http://infocenter.arm.com>.

All the described limitations are minor and related to the revision r0p1-v1 of the Cortex®-M4 CPU with FPU core. [Table 3](#) summarizes these limitations and their implications on the behavior of STM32F30xxx devices.

Table 3. Cortex®-M4F core limitations and impact on microcontroller behavior

ARM ID	ARM category	ARM summary of errata	Impact on STM32F3xxxx
752770	Cat B	Interrupted loads to SP can cause erroneous behavior	Minor
776924	Cat B	VDIV or VSQRT instructions might not complete correctly when very short ISRs are used	Minor

1.1 Cortex®-M4F interrupted loads to stack pointer can cause erroneous behavior

Description

An interrupt occurring during the data-phase of a single word load to the stack pointer (SP/R13) can cause an erroneous behavior of the device. In addition, returning from the interrupt results in the load instruction being executed with an additional time.

For all the instructions performing an update of the base register, the base register is erroneously updated on each execution, resulting in the stack pointer being loaded from an incorrect memory location.

The instructions affected by this limitation are the following:

- LDR SP, [Rn],#imm
- LDR SP, [Rn,#imm]!
- LDR SP, [Rn,#imm]
- LDR SP, [Rn]
- LDR SP, [Rn,Rm]

Workaround

As of today, no compiler generates these particular instructions. This limitation can only occur with hand-written assembly code.

Both issues can be solved by replacing the direct load to the stack pointer by an intermediate load to a general-purpose register followed by a move to the stack pointer.

Example:

Replace LDR SP, [R0] by

```
LDR R2,[R0]
```

```
MOV SP,R2
```

1.2 VDIV or VSQRT instructions might not complete correctly when very short ISRs are used

Description

On Cortex®-M4 with FPU core, 14 cycles are required to execute a VDIV or VSQRT instruction.

This limitation is present when the following conditions are met:

- A VDIV or VSQRT is executed
- The destination register for VDIV or VSQRT is one of s0 - s15
- An interrupt occurs and is taken
- The ISR being executed does not contain a floating point instruction
- 14 cycles after the VDIV or VSQRT is executed, an interrupt return is executed

In this case, if there are only one or two instructions inside the interrupt service routine, then the VDIV or VSQRT instruction does not complete correctly and the register bank and FPSCR are not updated, meaning that these registers hold incorrect out-of-date data.

Workaround

Two workarounds are applicable:

- Disable lazy context save of floating point state by clearing LSPEN to 0 (bit 30 of the FPCCR at address 0xE00EF34).
- Ensure that every ISR contains more than 2 instructions in addition to the exception return instruction.

2 STM32F318x8 silicon limitations

[Table 4](#) gives quick references to all documented limitations.

The legend for [Table 4](#) is as follows:

A = workaround available,

N = no workaround available,

P = partial workaround available,

'-' and grayed = fixed.

Table 4. Summary of silicon limitations

Links to silicon limitations		Revision Z
Section 2.1: System limitation	Section 2.1.1: Wakeup sequence from Standby mode when using more than one wakeup source	A
Section 2.2: ADC limitations	Section 2.2.1: Sampling time shortened in JAUTO auto delayed mode	A
	Section 2.2.2: Injected queue of context is not available in case of JQM = 0	N
	Section 2.2.3: Load multiple not supported by ADC interface	A
	Section 2.2.4: ADEN bit cannot be set immediately after the ADC calibration is done	A
Section 2.3: SPI peripheral limitation	Section 2.3.1: SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI is under DMA transaction near the end of transfer or end of transfer '-'	P
Section 2.4: I2C peripheral limitations	Section 2.4.1: 10-bit slave mode: wrong direction bit value after Read header reception	A
	Section 2.4.2: 10-bit combined with 7-bit slave mode: ADDCODE may indicate wrong slave address detection	N
	Section 2.4.3: Wakeup frames may not wakeup the MCU mode when STOP mode entry follows I2C enabling	A
	Section 2.4.4: Wrong behaviors in Stop mode when wakeup from Stop mode is disabled in I2C	A
	Section 2.4.5: Wakeup frame may not wakeup from STOP if tHD(STA) is close to tsu(HSI) in Fast-mode and Fast-mode Plus	P
	Section 2.4.6: Wrong data sampling when data set-up time (tSU;DAT) is smaller than one I2CCLK period	P
Section 2.5: I2S peripheral limitations	Section 2.5.1: In I2S slave mode, WS level must be set by the external master when enabling the I2S	A
Section 2.6: USART peripheral limitation	Section 2.6.1: When PCLK is selected as clock source for USART1, PCLK1 is used instead of PCLK2	A
Section 2.7: GPIO peripheral limitation	Section 2.7.1: GPIOx locking mechanism is not working properly for GPIOx_OTYPE register	A

2.1 System limitation

2.1.1 Wakeup sequence from Standby mode when using more than one wakeup source

Description

The various wakeup sources are logically OR-ed in front of the rising-edge detector that generates the wakeup flag (WUF). The WUF flag needs to be cleared prior to the Standby mode entry, otherwise the MCU wakes up immediately.

If one of the configured wakeup sources is kept high during the clearing of WUF flag (by setting the CWUF bit), it may mask further wakeup events on the input of the edge detector. As a consequence, the MCU may not be able to wake up from Standby mode.

Workaround

To avoid this limitation, the following sequence should be applied before entering the Standby mode:

- Disable all used wakeup sources.
- Clear all related wakeup flags.
- Re-enable all used wakeup sources.
- Enter Standby mode.

Note: when applying this workaround, if one of the wakeup sources is still kept high, the MCU will enter the Standby mode but then it will wake up immediately and generate the power reset.

2.2 ADC limitations

2.2.1 Sampling time shortened in JAUTO auto delayed mode

Description

When the ADC is configured in JAUTO single conversion mode (CONT=0), with auto delayed mode enabled (AUTDLY = 1), if the last regular conversion is read and a new regular trigger arrives before the JEOS bit is cleared, the first regular conversion sampling time is shortened by 1 cycle.

This does not apply for configuration where SMP = 000 (1.5 cycle sampling time), or if the interval between triggers is always above the auto-injected sequence conversion period.

Workaround

The sampling time can be increased by 1 clock cycle if the situation is foreseen.

2.2.2 Injected queue of context is not available in case of JQM = 0

Description

The queue mechanism is not functional when JQM = 0. The effective queue length is equal to 1 stage: a new context written before the previous context's consumption will lead to a queue overflow and will be ignored.

Consequently, the ADC must be stopped before programming the JSQR register.

Workaround

None.

2.2.3 Load multiple not supported by ADC interface

Description

The ADC interface only supports non-sequential read accesses.

Read accesses on AHB3 port (ADC interface) using Load multiple instruction are not supported.

The following sequence (read of JDR1, JDR2 and JDR3 injected data registers) will only cause the R1 register to be loaded with JDR1 value, and registers R2 and R3 will be zeroed.

```
LDR    R0 = 0x50000080
```

```
LDMIA  R0, {R1, R2, R3}
```

Workaround

Load multiple instruction LDMxx must be replaced by multiple single load (LD) instructions.

2.2.4 ADEN bit cannot be set immediately after the ADC calibration is done

Description

At the end of the ADC calibration, there is an internal reset of ADEN bit 4 ADC clock cycle after the ADCAL bit cleared by hardware.

Due to that, if ADEN bit is set within those four ADC clock cycles, it will be reset by the calibration logic and the ADC will stay disabled.

Workarounds

- Continue to set the ADEN bit, until ADRDY bit become '1'.
- After ADCAL is cleared, wait for a minimum of four ADC clock cycles before setting the ADEN bit.

2.3 SPI peripheral limitation

2.3.1 SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI is under DMA transaction near the end of transfer or end of transfer '-1'

Description

SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI is under DMA transaction near the end of transfer or end of transfer '-1'.

In the following conditions:

- SPI is slave or master,
- Full duplex or simplex mode is used,
- CRC feature is enabled,
- SPI is configured to manage data transfers by software (interrupt or polling),
- a peripheral, mapped on the same DMA channel as the SPI, is doing DMA transfers,

the CRC may be frozen before the CRCNEXT bit is written, resulting in a CRC error.

Workaround

If the application allows it, use the DMA for SPI transfers.

2.4 I²C peripheral limitations

2.4.1 10-bit slave mode: wrong direction bit value after Read header reception

Description

Under specific conditions, the transfer direction bit DIR (bit 16 of status register I2C_ISR) is low instead of high after reception of the 10-bit addressing Read header. Nevertheless, the I²C operates correctly in slave transmission mode, and data can be sent using the TXIS flag.

To see the limitation, all the following conditions have to be fulfilled:

- I²C has to be configured in 10-bit addressing mode (OA1MODE is set in the I2C_OAR1 register).
- The high LSBs of the I²C slave address are equal to the 10-bit addressing Read header value (i.e. OA1[7:3] = 11110, OA1[2] = OA1[9], OA1[1] = OA1[8] and OA1[0] = 1 in the I2C_OAR1 register).
- The I²C receives the 10-bit addressing Read header (0x 1111 0XX1) after the repeated start condition to enter slave transmission mode.

As a result, the DIR bit is incorrect in slave mode under specific conditions.

Workaround

If possible, do not use these four values as 10-bit addresses in slave mode:

- OA1[9:0] = 0011110001
- OA1[9:0] = 0111110011
- OA1[9:0] = 1011110101
- OA1[9:0] = 1111110111

If one of these addresses is the I²C slave address, the DIR bit must not be used in the FW.

2.4.2 10-bit combined with 7-bit slave mode: ADDCODE may indicate wrong slave address detection

Description

Under specific conditions, the ADDCODE (Address match code) in the I2C_ISR register indicates a wrong slave address.

To see the limitation, all the following conditions have to be fulfilled:

- The I²C slave address OA1 is enabled and configured in 10-bit mode (OA1EN=1 and OA1MODE=1)
- Another 7-bit slave address is enabled and the bits 1 to 7 of the 10-bit slave address OA1 are equal to the 7-bit slave address, i.e. one of the configurations below is set:
 - OA2EN=1 and OA2MSK = 0 and OA1[7:1] = OA2[7:1]
 - OA2EN=1 and OA2MSK = 1 and OA1[7:2] = OA2[7:2]
 - OA2EN=1 and OA2MSK = 2 and OA1[7:3] = OA2[7:3]
 - OA2EN=1 and OA2MSK = 3 and OA1[7:4] = OA2[7:4]
 - OA2EN=1 and OA2MSK = 4 and OA1[7:5] = OA2[7:5]
 - OA2EN=1 and OA2MSK = 5 and OA1[7:6] = OA2[7:6]
 - OA2EN=1 and OA2MSK = 6 and OA1[7] = OA2[7]
 - OA2EN=1 and OA2MSK = 7
 - GCEN=1 and OA1[7:1] = 0b0000000
 - ALERTEN=1 and OA1[7:1] = 0b0001100
 - SMBDEN=1 and OA1[7:1] = 0b1100001
 - SMBHEN=1 and OA1[7:1] = 0b0001000
- The master starts a transfer addressed to the 10-bit slave address OA1.

As a result, after the address reception, the ADDCODE value is OA1[7:1] equal to the 7-bit slave address, instead of 0b11110 & OA1[9:8].

Workaround

None. If several slave addresses are enabled, mixing 10-bit and 7-bit addresses, the 10-bit Slave address OA1 [7:1] must not be equal to the 7-bit slave address.

2.4.3 Wakeup frames may not wakeup the MCU mode when STOP mode entry follows I²C enabling

Description

If the I²C is enabled (PE = 1) and wakeup from STOP enabled in I²C (WUPEN=1) while a transfer occurs on the I²C bus and STOP mode is entered during the same transfer while SCL=0, the I²C is not able to detect the following START condition. This means that if the I²C is addressed, it will not wake up the MCU and this address is not acknowledged.

Workaround

After enabling the I²C (PE is set to 1), wait for a temporization before entering STOP mode, to ensure that the eventual on-going frame is finished.

2.4.4 Wrong behaviors in Stop mode when wakeup from Stop mode is disabled in I²C

Description

When wakeup from Stop mode is disabled in I2C (WUPEN = 0) and the MCU enters Stop mode while a transfer is on going on the bus, some wrong behaviors may happen:

1. BUSY flag can be wrongly set when the MCU exits Stop mode. This prevents from initiating a transfer in master mode, as the START condition cannot be sent when BUSY is set.
2. If clock stretching is enabled (NOSTRETCH = 0), the I2C clock SCL may be stretched low by the I2C as long as the MCU is in Stop mode. This limitation may occur when the Stop mode is entered during the address phase of a transfer on the I2C bus while SCL = 0. Therefore the transfer may be stalled as long as the MCU is in Stop mode. The probability of the occurrence depends also on the timings configuration, the peripheral clock frequency and the I2C bus frequency.

These behaviors can occur in Slave mode and in Master mode in a multi-master topology.

Workaround

Disable the I2C (PE=0) before entering Stop mode and re-enable it in Run mode.

2.4.5 Wakeup frame may not wakeup from STOP if $t_{HD(STA)}$ is close to $t_{su(HSI)}$ in Fast-mode and Fast-mode Plus

Description

Under specific conditions and if the START condition hold time $t_{HD(STA)}$ duration is very close to the HSI start-up time duration $t_{su(HSI)}$, the I²C is not able to detect the address match and to wake up the MCU from STOP. The $t_{su(HSI)}$ is between 1 μ s and 2 μ s (refer to product datasheet), therefore this issue cannot occur in Standard mode. To see the limitation, one of the conditions listed below has to be met:

- Timeout detection is enabled (TIMOUTEN=1 or TEXTEN=1) and the frame before the wakeup frame is abnormally finished due to a I²C Timeout detection (TIMOUT=1).
- The slave arbitration is lost during the frame before the wakeup frame (ARLO=1). According to standards, the slave arbitration is not applicable in I²C and used only in

SMBus, for which the transfer is done in Standard mode. Therefore when the standards are respected this condition does not lead to the limitation.

- The MCU enters STOP mode while another slave is addressed, after the address phase and before the STOP condition (BUSY=1).
- The MCU is in STOP mode and another slave is addressed before the I²C is addressed.

Note: *The last three conditions can occur only in a multi-slave network. In STOP mode, the HSI is powered on by the I²C when a START condition is detected (SDA falling edge while SCL is high). The HSI is used to receive the address and it is powered off after the address reception is case it is not the I²C slave address. If one of the conditions above is met and if the SCL falling edge following the START condition occurs on the first cycle of the I2CCLK clock (HSI), the address reception is not correctly done and the address match wakeup interrupt is not generated.*

Workaround

None at MCU level. To ensure the correct behavior in a multi-slave network, the master should use a START condition hold time lower than 1 μ s or greater than 2 μ s.

If the wakeup frame is not acknowledged by the I²C:

- If the master can program the duration of the START hold time: the master should decrease or increase the START condition hold time for more than one HSI period and resend the wakeup frame.
- If the master can change the I²C transfer mode: the master should switch to Standard mode and resend the wakeup frame.

2.4.6 Wrong data sampling when data set-up time ($t_{\text{SU;DAT}}$) is smaller than one I2CCLK period

Description

The I2C bus specification and user manual specifies a minimum data set-up time ($t_{\text{SU;DAT}}$) at:

- 250ns in Standard-mode,
- 100 ns in Fast-mode,
- 50 ns in Fast-mode Plus.

The I2C SDA line is not correctly sampled when $t_{\text{SU;DAT}}$ is smaller than one I2CCLK (I2C clock) period: the previous SDA value is sampled instead of the current one. This can result in a wrong slave address reception, a wrong received data byte, or a wrong received acknowledge bit.

Workaround

Increase the I2CCLK frequency to get I2CCLK period smaller than the transmitter minimum data set-up time. Or, if it is possible, increase the transmitter minimum data set-up time.

2.5 I2S peripheral limitations

2.5.1 In I2S slave mode, WS level must be set by the external master when enabling the I2S

Description

In slave mode, the WS signal level is used only to start the communication. If the I2S (in slave mode) is enabled while the master is already sending the clock and the WS signal level is low (for I2S protocol) or high (for the LSB- or MSB-justified mode), the slave starts communicating data immediately. In this case, the master and slave will be desynchronized throughout the whole communication.

Workaround

The I2S peripheral must be enabled when the external master sets the WS line at:

- High level when the I2S protocol is selected.
- Low level when the LSB- or MSB-justified mode is selected.

2.6 USART peripheral limitation

2.6.1 When PCLK is selected as clock source for USART1, PCLK1 is used instead of PCLK2

Description

USART1 is mapped on the fast APB (APB2) and its clock can be selected among four different sources using the USART1SW [1:0] bits in the RCC_CFGR3 register.

The default configuration selects PCLK1 (APB1 clock) as USART1 clock source instead of PCLK2 (APB2 clock).

Workaround

There is no workaround. To reach 9 Mbaud, System Clock (SYSCLK) should be selected as USART1 clock source.

2.7 GPIO peripheral limitation

2.7.1 GPIOx locking mechanism is not working properly for GPIOx_OTYPE register

Description

Locking of GPIOx_OTYPER[i] with i = 15..8 depends on the setting of GPIOx_LCKR[i-8] and not from the setting of GPIOx_LCKR[i]. GPIOx_LCKR[i-8] locks GPIOx_OTYPER[i] together with GPIOx_OTYPER[i-8]. It is not possible to lock GPIOx_OTYPER[i] with i = 15...8, without locking also GPIOx_OTYPER[i-8].

Workaround

The only way to lock GPIOx_OTYPER[i] with i=15..8 is to lock also GPIOx_OTYPER[i-8].

Revision history

Table 5. Document revision history

Date	Revision	Changes
27-May-2014	1	Initial release.
10-Jun-2014	2	Added <i>Section 1.2: VDIV or VSQRT instructions might not complete correctly when very short ISRs are used</i> and <i>Section 2.4.6: Wrong data sampling when data set-up time (tSU;DAT) is smaller than one I2CCLK period.</i> Updated <i>Table 3: Cortex®-M4F core limitations and impact on microcontroller behavior.</i>
21-Nov-2014	3	Added note ⁽²⁾ in <i>Table 1: Device identification</i> Removed package marking information. Added the following limitations: <ul style="list-style-type: none"> – <i>Section 2.1.1: Wakeup sequence from Standby mode when using more than one wakeup source</i> – <i>Section 2.2.3: Load multiple not supported by ADC interface</i> – <i>Section 2.3.1: SPI CRC may be corrupted when a peripheral connected to the same DMA channel of the SPI is under DMA transaction near the end of transfer or end of transfer '-1'</i> – <i>Section 2.2.4: ADEN bit cannot be set immediately after the ADC calibration is done</i>

IMPORTANT NOTICE – PLEASE READ CAREFULLY

STMicroelectronics NV and its subsidiaries ("ST") reserve the right to make changes, corrections, enhancements, modifications, and improvements to ST products and/or to this document at any time without notice. Purchasers should obtain the latest relevant information on ST products before placing orders. ST products are sold pursuant to ST's terms and conditions of sale in place at the time of order acknowledgement.

Purchasers are solely responsible for the choice, selection, and use of ST products and ST assumes no liability for application assistance or the design of Purchasers' products.

No license, express or implied, to any intellectual property right is granted by ST herein.

Resale of ST products with provisions different from the information set forth herein shall void any warranty granted by ST for such product.

ST and the ST logo are trademarks of ST. All other product or service names are the property of their respective owners.

Information in this document supersedes and replaces information previously supplied in any prior versions of this document.

© 2014 STMicroelectronics – All rights reserved