

# EFM8 Sleepy Bee Family EFM8SB1 Errata



This document contains information on the errata of revision A of EFM8SB1.

For errata on older revisions, please refer to the errata history for the device. The device data sheet explains how to identify chip revision, either from package marking or electronically.

Errata effective date: February 24, 2015.

# ERRATA DEFINITIONS

Impact Definition: Each erratum is marked with an impact as defined below:

- · Minor—Workaround exists.
- Major—Errata that do not conform to the data sheet or standard.
- Information—The device behavior is not ideal but acceptable. Typically, the data sheet will be changed to match the device behavior.

Table .1. Errata Status Summary

Errata #	Title/Problem	Effect	Fix/Workaround
1	UART Bootloader Not Available	Major	A bootloader is not required for normal operation. However, if a bootloader is required, download a bootloader to the device flash.

#### 1. UART Bootloader Not Available

#### **Description of Errata**

The revision 1.1 data sheet mentions a UART bootloader in device flash. This bootloader is not yet available.

### **Affected Conditions / Impacts**

A bootloader is not required for normal operation. Systems intending to use the the pre-programmed UART bootloader will need to implement and download a bootloader to the devices received from the factory.

#### Workaround

A bootloader is not required for normal operation. However, if a bootloader is required by the application, a custom-written bootloader can be downloaded to devices received from the factory.

# Resolution

This issue will be resolved in devices that display a future, to-be-determined date code. Details will be released when additional information is available.











#### Disclaimer

Silicon Laboratories intends to provide customers with the latest, accurate, and in-depth documentation of all peripherals and modules available for system and software implementers using or intending to use the Silicon Laboratories products. Characterization data, available modules and peripherals, memory sizes and memory addresses refer to each specific device, and "Typical" parameters provided can and do vary in different applications. Application examples described herein are for illustrative purposes only. Silicon Laboratories reserves the right to make changes without further notice and limitation to product information, specifications, and descriptions herein, and does not give warranties as to the accuracy or completeness of the included information. Silicon Laboratories shall have no liability for the consequences of use of the information supplied herein. This document does not imply or express copyright licenses granted hereunder to design or fabricate any integrated circuits. The products must not be used within any Life Support System without the specific written consent of Silicon Laboratories. A "Life Support System" is any product or system intended to support or sustain life and/or health, which, if it fails, can be reasonably expected to result in significant personal injury or death. Silicon Laboratories products are generally not intended for military applications. Silicon Laboratories products shall under no circumstances be used in weapons of mass destruction including (but not limited to) nuclear, biological or chemical weapons, or missiles capable of delivering such weapons.

## Trademark Information

Silicon Laboratories Inc., Silicon Laboratories, Silicon Labs, SiLabs and the Silicon Labs logo, CMEMS®, EFM, EFM32, EFR, Energy Micro, Energy Micro logo and combinations thereof, "the world's most energy friendly microcontrollers", Ember®, EZLink®, EZMac®, EZRadio®, EZRadioPRO®, DSPLL®, ISOmodem ®, Precision32®, ProSLIC®, SiPHY®, USBXpress® and others are trademarks or registered trademarks of Silicon Laboratories Inc. ARM, CORTEX, Cortex-M3 and THUMB are trademarks or registered trademarks of ARM Holdings. Keil is a registered trademark of ARM Limited. All other products or brand names mentioned herein are trademarks of their respective holders.



Silicon Laboratories Inc. 400 West Cesar Chavez Austin, TX 78701 USA